




JAIL CONDITION ANALYSIS AND RENOVATION REVIEW

January 28, 2025
Travis Parker, Facilities Director



TODAY'S OBJECTIVE

- To provide an in-depth review of the current condition of the jail facility and outline potential upgrades and renovation plans to address identified needs and ensure long-term functionality.






BACKGROUND

- 314,000 SQFT Facility
- 1,148 Beds
- New - 1999
- Upgrade - 2007
- Upgrade - 2009



15 Years since last significant upgrade and/or improvement.



THE FACILITY



THE FACILITY




Breakdown

- Breaking down the main components of a renovation enables us to systematically address the 314,000-square-foot facility.



Mechanical



Electrical




Plumbing



Building
Envelope



Other



MECHANICAL

MECHANICAL UPGRAGES


- Heating/Cooling Systems
 - Boiler
 - Chiller
 - RTU
 - Dampers
 - Actuators
- Building Automation

ESTIMATED TOTAL:

\$30 Million



EXAMPLES



A perspective view of a long row of industrial electrical control cabinets. The cabinets are light-colored with dark doors. Many have yellow warning labels with a lightning bolt symbol. Some doors are open, revealing internal components like circuit boards and wires. The background shows a factory interior with a steel truss ceiling.

ELECTRICAL



ELECTRICAL UPGRADES

- Lighting Systems
- Electrical Panels
- Wiring and Circuits
- Backup Generation
- Security Systems
- Access Control Systems
- Data/Communication Infrastructure

**ESTIMATED TOTAL:
\$7.7 MILLION**



EXAMPLES



A photograph showing a dense network of copper pipes and insulation within a wall or ceiling structure. The pipes are primarily copper, with some white plastic components. They are secured to a light-colored wooden joist or wall studs with metal straps. The insulation consists of white mineral wool or fiberglass batts. The overall appearance is that of a professional plumbing or HVAC installation.

PLUMBING

PLUMBING UPGRADES

- Water Supply Lines
- Sanitary Sewer Lining
- Icon System
- Water Heaters
- Etc.

**ESTIMATED TOTAL:
\$15 MILLION**



EXAMPLES



BUILDING ENVELOPE

BUILDING ENVELOPE UPGRADES

- Miscellaneous Block Repair
- Roofing Replacement
- Flooring Repair and Replacement
- Door System Upgrades

**ESTIMATED TOTAL:
\$21 MILLION**



EXAMPLES





OTHER





Contents

- Kitchen Equipment
 - Renovation
 - Upgrade
- Commercial Washing Equipment
- Infrastructure
 - IT/Data
 - Communication
 - Misc.





**ESTIMATED TOTAL:
\$8 MILLION**

EXAMPLES



EXAMPLES



Other Considerations

- Hard Costs
 - Construction Materials & Labor
 - Equipment Replacement.
 - Specialty Work
- Soft Costs
 - Design & Engineering Fees
 - Permitting and Inspection
 - Project Management
 - Contingency
- Project Phasing



ESTIMATED TOTAL:
\$81.7 MILLION